

# General Environmental Incident Summary

**Incident:** 1344      **Notice:** 1/6/2011      1100      **Occurred:** 1/1/2011      0900

**DEM Incident No:**

**No Further Action:** ☒

**Responsible Party:** Grandview Enterprises, Inc

**County:** Burleigh

**TwP Rng Sec Qtr:** 139 80 25 NE NW SW

**Lat Long + Method:** 46.83073 -100.72020 Derived from TRS

**Location Description:** approximately 4000 E. Divide Avenue, Bismarck North Dakota

**Submitted By Info:** Lila Marquart  
WPC Inc

## Received By Info:

**Contact Info:** Jim Hilts  
7708 NE 99th St  
Vancouver WA 98662

**Affected Medium:** 09 - other

**Near. Occupied Bldg:** 100 Feet

**Type of Incident:** Fuel Line Leak

**Release Contained:**

**Reported to NRC:** No

**Contaminant:** diesel fuel

**Volume of Release:** 75 gallons

**Duration of Release:** 84 hours

**Agriculture Related:** No

**EPA Extremely**

**Hazardous Substance:** No

**Number of Fatalities:** 0

**Number of Injuries:** 0

## Cause of Incident:

Semi-Truck parked on Divide Avenue overnight due to storm on Friday night, 12/31/10. Driver discovered fuel release in morning. Fuel leak from one of saddle tanks on truck was dripping diesel. Due to holiday and weather, trucker was unable to get leak repaired until Tuesday, 1/4/11. Final cleanup on 1/4/11 after truck was removed.

## Risk Evaluation:

Immediate risk was ignitable hazard from volatile organic vapors. Vapors were controlled with absorbents. Snow and ice limited the diesel to the street. No soil, storm drains or surface water were impacted.

## Potential Env. Impacts:

All impacted snow and ice was removed for disposal. No likelihood of further impact, other than minor staining to the pavement on the street.

## Action Taken/Planned:

Environmental consultant responded. Absorbents were used to contain the fuel. Fuel, absorbents, snow and ice were collected and trucked off site. Snow and ice cover limited the area the diesel could spread to the street.

## Wastes Disposal Location:

Diesel contaminated absorbents, snow and ice were taken to the Bismarck Municipal Solid Waste Landfill, where they were accepted for disposal.

***Other Agencies Involved:***

Local Fire Department, Local Env. Health Office

***Updates***

---

***Date:*** 6/18/2019      ***Status:*** Inspection

***Author:*** Schiermeister, Robin

***Notes:***

Arrived on 6-18-2019 at 15:33. It was cloudy with temperatures in the 70s. Walked to the described location in the report and saw no signs of contamination. Vegetation is also green and actively growing. Due to these reasons this incident needs no further follow-up.

***Updated Volume:*** None at the time of this update